



**JABATAN LAUT MALAYSIA**  
IBU PEJABAT LAUT  
PETI SURAT 12, JALAN LIMBUNGAN  
42007 PELABUHAN KLANG  
SELANGOR DARUL EHSAN



## NOTICE TO MARINERS      NTM 185(T)/2022

Telefon           : 03-3346 7777    Emel               : [kpgr@marine.gov.my](mailto:kpgr@marine.gov.my)  
Faksimili        : 03-3168 5289    Laman Web      : <http://www.marine.gov.my>

---

Authority           : Director of Marine, Malaysia

Position           : Lumut Waters

Charts Affected   : MAL 5425  
                          BA 3944

---

### VALE FAIRWAY LIGHT BUOY DAMAGED LUMUT WATERS

---

Mariners are advised that Vale Fairway Light buoy has been damaged.

Name                : Vale Fairway  
Position            : Lat.    04° 08.905' N  
                          Long. 100° 32.880' E

Mariners are advised to navigate with caution when in the vicinity.

**(MOHD IZUAN BIN ISNAN)**  
for The Director General,  
Marine Department Malaysia.  
25<sup>th</sup> November 2022

---

*Safer Ship*



*leaner Seas*

CERTIFIED TO ISO 9001:2015  
CERT. NO.: QMS 03602