



**HYDROGRAPHIC OFFICE
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422
Website: www.marine.gov.my



BORNEO NORTH WEST COAST

160/2021(T) – LEBEAN - SPECIAL MARK BUOY DAMAGE AND UNLIT

The top structure of Lebaan Special Mark Buoy at position 02°17'15.565"N 111°42'14.436"E is reported damage and unlit.

2. Mariners are advised to navigate with caution when in the vicinity.

Charts : SAR 2, SAR 5 & SAR 1441

Source : Sarawak Rivers Board

Date : 27th October 2021

" BERKHIDMAT UNTUK NEGARA "

[MUHAMAD SAHABULLAH BIN KASIM]

For Director of Marine Sarawak

"Safer Ships, Secure Ports, Cleaner Seas"



Cert. No: ISO 9001-0047621, ISO 9001-0047600