



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 152/2022

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : South China Sea

Charts Affected : MAL 6416
 BA 1374

BUKIT PEJAJAT LIGHT BEACON RESTORED TO NORMAL KEMAMAN PORT, TERENGGANU

Mariners are advised that Bukit Pejjat Lightbeacon has been restored to normal.

Name : Bukit Pejjat
Position : Lat. 04° 14.270' N
 Long. 103° 27.314' E
Light Characteristic : Fl.W.12s

Mariners are advised to navigate with caution in the area.

This notice cancels NTM 139(T)/2022.

(MOHD IZUAN BIN ISNAN)
for The Director General,
Marine Department Malaysia.
6th Oktober 2022

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602