



**JABATAN LAUT MALAYSIA**  
**IBU PEJABAT LAUT**  
**PETI SURAT 12, JALAN LIMBUNGAN**  
**42007 PELABUHAN KLANG**  
**SELANGOR DARUL EHSAN**



## **NOTICE TO MARINERS      NTM 126/2022**

Telefon           : 03-3346 7777    Emel               : [kpqr@marine.gov.my](mailto:kpqr@marine.gov.my)  
Faksimili        : 03-3168 5289    Laman Web      : <http://www.marine.gov.my>

---

Authority           : Director of Marine, Malaysia

Position           : Malacca Strait

Charts Affected   : MAL 532  
                          BA 3902

---

### **NO. 3 PORT DICKSON LIGHT BUOY RESTORED TO NORMAL MALACCA STRAIT**

---

Mariners are advised that No.3 Port Dickson Light Buoy has been restored to normal.

Name                : No.3 Port Dickson Light Buoy

Position            : Lat.    02° 31.000' N  
                          Long. 101° 46.390' E

Light Characteristic : Fl(3).G.10s

Mariners are advised to navigate with caution when in the vicinity.

This notice cancels NTM 120(T)/2022.

**(EMIZUL FADLY BIN MASDEK)**

for The Director General,  
Marine Department Malaysia.  
24<sup>th</sup> August 2022

---

*Safer Ships, Secure Ports, Cleaner Seas*



CERTIFIED TO ISO 9001:2015  
CERT. NO.: QMS 03602