



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 30(T)/2023

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : Malacca Strait
Charts Affected : MAL 532
 BA 3946

SEPAT RLB LIGHTBEACON REDUCED POWER MALACCA STRAIT

Mariners are advised that Sepat RLB Lightbeacon is temporarily operating on reduced power.

Name : Sepat RLB Lightbeacon
Position : Lat. 02° 33.889' N
 Long. 101° 23.363' E
Characteristic : Q.W

Mariners are advised to navigate with caution.

(Ts. MUHAMMAD FADHLI BIN MAKHTAR)
for The Director General,
Marine Department Malaysia.
15th Mac 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602