



JABATAN LAUT SEMENANJUNG MALAYSIA  
Pejabat Laut Wilayah Persekutuan Labuan,  
Peti Surat 81005, 87008 Wilayah Persekutuan Labuan.

Telefon : +6 087 – 413 511 Emel : [pilwplbn@marine.gov.my](mailto:pilwplbn@marine.gov.my)  
Faks : +6 087 – 413 515 Laman Web : [www.marine.gov.my](http://www.marine.gov.my)

## PEKELILING PELABUHAN PORT CIRCULAR

### NO. 05/2007



MS ISO 9001  
Approval Cert. No : 403591 A  
Approval Cert. No : 403591 C  
Approval Cert. No : 403591 D

## LIGHT BUOY (EAST CH. NO.1 (G) TEMPORARILY UNLIT

### BOYA BERLAMPU (EAST CH. NO.1 (G) TIDAK MENYALA SEMENTARA

Daripada : Pengarah Laut  
*From* : *Director of Marine*  
Kepada : Masyarakat Perkapalan / Pengguna-Pengguna Pelabuhan  
*To* : *Shipping Community/ Ports User*  
Tarikh : 16hb February, 2007  
*Date* : *16th February, 2007*  
Carta Berkaitan : BA 947, MAL 8518  
*Effective Chart*

Masyarakat perkapalan dimaklumkan bahawa boya berlampu (East Ch. No.1 (G) tidak menyala sementara.

Nama : East Ch. No.1 (G)  
Kedudukan : Lat. 05<sup>0</sup> 18.20' Utara  
Long. 115<sup>0</sup> 16.94' Timur  
(*Timbalai Datum*)

Sifat lampu : FL (G) 5s 4M

Sehubungan itu, semua kapal, feri dan bot adalah dinasihat supaya belayar dengan lebih berhati-hati.

Shipping community is hereby notified that light buoy (East Ch. No.1 (G) **temporarily unlit.**

Name : (East Ch. No.1 (G)  
Position : Lat. 05<sup>0</sup> 18.20' North  
Long. 115<sup>0</sup> 16.94' East  
(*Timbalai Datum*)

Light Characteristic : FL.(G) 5s 4M

All vessels, passenger ferries, passenger boats and any other type of water crafts are advised to exercise extra caution when proceeding in the vicinity.

(ABDUL AZIZ BIN MUHAMUD)  
Director of Marine  
Marine Department of Labuan Federal Territory