



**JABATAN LAUT MALAYSIA**  
**IBU PEJABAT LAUT**  
**PETI SURAT 12, JALAN LIMBUNGAN**  
**42007 PELABUHAN KLANG**  
**SELANGOR DARUL EHSAN**



## **NOTICE TO MARINERS      NTM 152/2021**

Telefon           : 03-3346 7777    Emel               : [kpqr@marine.gov.my](mailto:kpqr@marine.gov.my)  
Faksimili        : 03-3168 5289    Laman Web     : <http://www.marine.gov.my>

---

Authority           : Director of Marine, Malaysia

Position           : Labuan Waters

Charts Affected   : MAL 864 & MAL 8518  
                          BA 211

---

### **ISOLATED DANGER MARK LIGHT BUOY ESTABLISHED LABUAN WATERS**

---

Mariners are advised that a new isolated danger mark light buoy has been established:

Name               : SOO YUAN 220

Type                : Isolated Danger Mark

Position           : Lat. 05° 14.388' N, Long. 115° 17.267' E  
(WGS 84)

Light Characteristic : Fl (2)W.8s

Mariners are advised to take extra caution when navigating in the vicinity.

**(MOHD IZUAN BIN ISNAN)**  
for The Director General,  
Marine Department Malaysia.  
1<sup>st</sup> September 2021

---

*Safer Ships, Secure Ports, Cleaner Seas*



CERTIFIED TO ISO 9001:2015  
CERT. NO.: QMS 03602