



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 179/2021

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Port Klang Waters

Charts Affected : MAL 540
 BA 3945

SOUTH CARDINAL BUOY ESTABLISHED PORT KLANG WATERS

Mariners are advised that a new South Cardinal buoy has been established:

Name : Ocean Serene Wreck
Type : South Cardinal Buoy
Position : Lat. 02° 59.784' N, Long. 101° 22.865' E
 (WGS 84)
Light Characteristic : Q(6)+ LFl.15s

Mariners are advised to take extra caution when navigating in the vicinity.

(MOHD IZUAN BIN ISNAN)
for The Director General,
Marine Department Malaysia.
27th September 2021

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602