



**HYDROGRAPHIC OFFICE  
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS  
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422  
Website: www.marine.gov.my



**BORNEO NORTH WEST COAST**

**147/2021(T) – SAMALAJU PORT – BUOY MISSING**

Lateral Mark Buoy SIP 8, Fl. 5s at position 03° 35' 16.700"N, 113° 18' 14.700"E, is reported missing.

2. Mariners are advised to navigate with caution when in the vicinity.

Charts : SAR 401, SAR 402 & SAR 4001  
Source : Sarawak Marine Department  
Date : 30<sup>th</sup> September 2021

**" BERKHIDMAT UNTUK NEGARA "**

**[ RADUAN BIN SERAP ]**  
For Director of Marine Sarawak

***"Safer Ships, Secure Ports, Cleaner Seas"***



Cert. No: ISO 9001-0047621, ISO 9001-0047600