



**HYDROGRAPHIC OFFICE
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422
Website: www.marine.gov.my



BORNEO NORTH WEST COAST

58/2021(T) – STARBOARD LATERAL MARK SIP 3 BUOY, SAMALAJU PORT - MISSING

Starboard Lateral Mark SIP 3 Buoy Fl. 5s at position 03°36'08.300"N
113°17'13.400"E, Samalaju Port was reported missing.

2. Mariners are advised to navigate with caution in the area.

Charts : SAR 501 & SAR 5001

Source : Sarawak Marine Department

Date : 30th April 2021

" BERKHIDMAT UNTUK NEGARA "

[MUHAMAD SAHABULLAH BIN KASIM]

For Director of Marine Sarawak

"Safer Ships, Secure Ports, Cleaner Seas"



Cert. No: ISO 9001-0047621, ISO 9001-0047600