



**HYDROGRAPHIC OFFICE  
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS  
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422  
Website: [www.marine.gov.my](http://www.marine.gov.my)



**BORNEO NORTH WEST COAST**

**66/2022(T) – BUOY Y5, BINTULU PORT – MISSING**

Buoy Y5 at position 03°15'58.024"N 113°03'50.471"E is reported missing. Mariners are advised to navigate with caution in the area.

Charts : SAR 6, SAR 401, SAR 402 & SAR 4001  
Source : Sarawak Region Marine Department  
Date : 12<sup>th</sup> May 2022

**"BERKHIDMAT UNTUK NEGARA"**

**[ RADUAN BIN SERAP ]**  
For Director of Marine Sarawak

**“Safer Ships, Secure Ports, Cleaner Seas”**



Cert. No: ISO 9001-0047621, ISO 9001-0047600