



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 76/2022

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Kuantan Waters

Charts Affected : MAL 635
 BA 2422

KUANTAN PORT OUTER FAIRWAY LIGHT BUOY RE-ESTABLISHED IN POSITION KUANTAN, PAHANG

Mariners are advised that Kuantan Port Outer Fairway Light Buoy has been re-established in position.

Name : Kuantan Port Outer Fairway Light Buoy

New Position : Lat. 03° 54.749' N
 Long. 103° 33.193' E

Light Characteristic : ISO.W.6s

Description : Fairway

This notice cancels NTM 29(R)/2022

Mariners are advised to navigate with caution when in the vicinity.

(MOHD IZUAN BIN ISNAN)
for The Director General,
Marine Department Malaysia.
30th May 2022

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602