



**HYDROGRAPHIC OFFICE
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422
Website: www.marine.gov.my



BORNEO NORTH WEST COAST

***93/2022 – RETRIEVAL OF SUNKEN VESSEL OF MV GEOS WITH CARDINAL MARKS BUOY DEPLOYED AT THE ACTIVITIES AREA AT MIRI WATER**

1. Delete:

Buoy	Latitude	Longitude	Light Characteristic	Symbol
Isolated Danger Mark	4°40'22.680"N	113°58'36.600"E	Fl(2).W.8s3M	

Positions in WGS 84 Datum

2. Insert:

Buoy	Latitude	Longitude	Light Characteristic	Symbol
CB 1 (North)	4°40'33.060"N	113°58'21.840"E	Q	
CB 2 (East)	4°40'30.900"N	113°58'42.780"E	Q(3)10s	
CB 3 (South)	4°40'12.480"N	113°58'43.020"E	Q(6)+LFl.15s	
CB 4 (West)	4°40'13.740"N	113°58'24.900"E	Q(9)15s	

Positions in WGS 84 Datum

3. Notices *161/2021 is cancelled and mariners are advised to update their affected charts accordingly.

Charts : SAR 1, SAR 2, SAR 4, SAR 7, SAR 420 & SAR 7100
Source : Bumi Jaya Salvage & Engineering Sdn. Bhd.
Date : 11th August 2022

"BERKHIDMAT UNTUK NEGARA"

[RADUAN BIN SERAP]
For Director of Marine Sarawak

"Safer Ships, Secure Ports, Cleaner Seas"



Cert. No: ISO 9001-0047621, ISO 9001-0047600