



NOTICE TO MARINERS NTM 178T/2021

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
 Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Port Klang Waters

Charts Affected : MAL 540
 BA 3945

**BUOY POSITION TEMPORARY ALTERED
 PORT KLANG WATERS**

Mariners are advised that the position for the following buoy have been temporary altered.

Buoy Name	Current Position	Temporary Position
Buas-Buas	Lat. 02° 53.760' N Long. 101° 15.970' E	Lat. 02° 53.760' N Long. 101° 16.060' E
Tenteram	Lat. 02° 53.820' N Long. 101° 15.670' E	Lat. 02° 53.820' N Long. 101° 15.590' E
Tengah	Lat. 02° 52.670' N Long. 101° 15.440' E	Lat. 02° 52.670' N Long. 101° 15.360' E
Terusan	Lat. 02° 51.510' N Long. 101° 15.210' E	Lat. 02° 51.510' N Long. 101° 15.130' E
Pintu Gedong	Lat. 02° 51.460' N Long. 101° 15.480' E	Lat. 02° 51.460' N Long. 101° 15.570' E
Selat	Lat. 02° 52.610' N Long. 101° 15.700' E	Lat. 02° 52.610' N Long. 101° 15.800' E
No. 2	Lat. 03° 10.530' N Long. 101° 14.740' E	Lat. 02° 10.590' N Long. 101° 14.790' E
No. 4	Lat. 03° 09.660' N Long. 101° 15.720' E	Lat. 03° 09.710' N Long. 101° 15.780' E
No. 8	Lat. 03° 05.360' N Long. 101° 19.370' E	Lat. 03° 05.410' N Long. 101° 19.430' E
Elbow	Lat. 03° 02.440' N Long. 101° 20.910' E	Lat. 03° 02.410' N Long. 101° 20.840' E

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
 CERT. NO.: QMS 03602

Mariners are advised to navigate with caution when in the vicinity.

(MOHD IZUAN BIN ISNAN)
for The Director General,
Marine Department Malaysia.
27Th September 2021