



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 131(T)/2021

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : Malacca Strait
Charts Affected : MAL 521 & MAL 54
 BA 3947, BA 3946 & BA 1358

PULAU UN DAN LIGHTHOUSE REDUCED POWER MALACCA STRAIT

Mariners are advised that Pulau Undan Lighthouse is temporarily operating on reduced power and light nominal range is reduced to 15 nautical miles.

Name : Pulau Undan Lighthouse
Position : Lat. 02° 02.900' N
 Long. 102° 20.100' E
Characteristic : Fl(2).W.15s

Mariners are advised to navigate with caution.

(RINA MASLINA BINTI BAHARUDIN)
for The Director General,
Marine Department Malaysia.
27th July 2021

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602