

JABATAN LAUT SEMENANJUNG MALAYSIA  
PEJABAT LAUT WILAYAH UTARA  
JALAN AKUARIUM GELUGUR,  
PETI SURAT 765,  
10790 PULAU PINANG

Fax : 04-6575521  
Telefon : 04-6578494  
E-mail : pjlwut@marine.gov.my

**PEKELILING PELABUHAN NO. 7 TAHUN 1999**

---

DARIPADA: PENGARAH LAUT WILAYAH UTARA , PULAU PINANG.

KEPADA : MASYARAKAT PERKAPALAN WILAYAH UTARA

(PULAU PINANG , KEDAH , PERLIS DAN PERAK)

TARIKH : 20 MEI 1999.

---

**TANDARAH SUAR DI PULAU KATAK TIDAK MENYALA**

1. Masyarakat perkapalan adalah dimaklumkan bahawa tandarah suar di Pulau Katak adalah tidak berfungsi untuk sementara waktu.
2. Butir-butir tandarah suar tersebut adalah seperti berikut:

Nama : **Tandarah Suar Pulau Katak**

Posisi : **Lat 4° 9.2' Utara**

**Long 100° 37.4 Timur**

Struktur : **Konkrit**

Sifat Lampu : **FL3s**

3. Semua kapal yang melalui kawasan tersebut hendaklah belayar dengan berhati-hati.

**BEACON AT PULAU KATAK TEMPORARILY UNLIT**

1. Mariners are notified that beacon at Pulau Katak is temporarily unlit.
2. Particulars of the beacon are as follows:

Name : **Tandarah Suar Pulau Katak**

Position : **Lat 4° 9.2" Utara**

**Long 100° 37.4" Timur**

Structure : **Konkrit**

Light Characteristic : **FL3s**

3. Mariners are advised to exercise caution while navigating in this vicinity.

**HAJI JAMALUDIN BIN YUSUF.**

b.p. Pengarah Laut Wilayah Utara , Pulau Pinang.