



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 89/2022

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Port Klang Waters

Charts Affected : MAL 540
 BA 3945

SOUTH CARDINAL BUOY PERMANENTLY WITHDRAWN PORT KLANG WATERS

Mariners are advised that the South Cardinal Buoy have been permanently withdrawn.

Name : Ocean Serene Wreck
Type : South Cardinal Buoy
Position : Lat. 02° 59.784' N, Long. 101° 22.865' E (WGS 84)
Light Characteristic : Q(6)+ LFl.15s

This notice cancels NTM 179/2021.

Mariners are advised to navigate with caution when in the vicinity.

(EMIZUL FADLY BIN MASDEK)
for The Director General,
Marine Department Malaysia.
30th June 2022

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602