



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS

NTM 86(T)/2021

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Pahang Waters

Charts Affected : MAL 635
BA 3445

KUALA ROMPIN 2G LIGHT BUOY TEMPORARILY WITHDRAWN PAHANG WATERS

Mariners are advised that Kuala Rompin 2G Light Buoy is temporarily withdrawn.

Name : Kuala Rompin 2G Light Buoy

Position : Lat. 02° 49.105' N
Long. 103° 28.625' E

Light Characteristic : Fl.G.4s

Mariners are advised to navigate with caution in the area.

(RINA MASLINA BINTI BAHARUDIN)

for The Director General,
Marine Department Malaysia.
15th May 2021

Safer Ships, Safer Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602