



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 114/2021

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : South China Sea

Charts Affected : MAL 635
 BA 3446 & BA 1379

KUANTAN PORT FAIRWAY INNER LIGHT BUOY RE-ESTABLISHED IN POSITION KUANTAN PORT, PAHANG

Mariners are advised that Kuantan Port Fairway Inner Light Buoy has been re-established in position.

Name : Kuantan Port Fairway Inner

Position : Lat. 03° 55.520' N
 Long. 103° 29.150' E

Light Characteristic : L.FL.10s

This notice cancels NTM 06(T)/2021

(MOHD FAIZAL BIN MOHD NASIR)
for The Director General,
Marine Department Malaysia.
29th June 2021

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602