



**HYDROGRAPHIC OFFICE
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422
Website: www.marine.gov.my



BORNEO NORTH WEST COAST

76/2022(T) – STARBOARD LATERAL MARK BUOY SIP 9, SAMALAJU PORT – MISSING

Starboard Lateral Mark Buoy SIP 9 at position 03°34'41.800"N 113°18'38.300"E is reported missing. Mariners are advised to navigate with caution in the area.

Charts : SAR 501 & SAR 5001
Source : Sarawak Region Marine Department
Date : 21st June 2022

"BERKHIDMAT UNTUK NEGARA"

[RADUAN BIN SERAP]
For Director of Marine Sarawak

“Safer Ships, Secure Ports, Cleaner Seas”



Cert. No: ISO 9001-0047621, ISO 9001-0047600