



**HYDROGRAPHIC OFFICE
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422
Website: www.marine.gov.my



BORNEO NORTH WEST COAST

25/2021(T) – BUOY K, SOUTH ACCESS CHANNEL, BINTULU PORT - MISSING

Buoy K Fl. G. 5s 03°15'08.440"N 113°02'33.201"E, South Access Channel, Bintulu Port is missing. Mariners are advised to navigate with caution in the area.

Charts : SAR 401, SAR 402 & SAR 4001

Source : Sarawak Marine Department

Date : 09th March 2021

" BERKHIDMAT UNTUK NEGARA "

[RADUAN BIN SERAP]

For Director of Marine Sarawak

"Safer Ships, Secure Ports, Cleaner Seas"



Cert. No: ISO 9001-0047621, ISO 9001-0047600