



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 143(T)/2021

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Port Kelang, Selangor

Charts Affected : MAL 532, 5300
 BA 3946

SELAT LIGHT BUOY DESTROYED PORT KELANG, SELANGOR

Mariners are advised that Selat Light Buoy has been destroyed. The details are as follows:

Name : Selat Light Buoy

Position : Lat. 02° 52.600' N
 Long. 101° 15.720' E

Light Characteristic : ISO.G.5s

Mariners are advised to navigate with caution in the area.

(MOHD FAIZAL BIN MOHD NASIR)

for The Director General,
Marine Department Malaysia.
20th August 2021

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602