



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 195/2022

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Port Klang waters

Charts Affected : MAL 5300
 BA 3945

TENTERAM LIGHT BUOY RESTORED TO NORMAL PORT KLANG WATERS

Mariners are advised that Tenteram Light Buoy has been restored to normal.

Name : Tenteram

Position : Lat. 02° 53.50' N
 Long. 101° 15.48' E

Light Characteristic : Fl(3).R.10s

Mariners are advised to navigate with caution in the area.

This notice cancels NTM 188(T)/2022

(MOHD IZUAN BIN ISNAN)
for The Director General,
Marine Department Malaysia.
1st December 2022

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602