



**JABATAN LAUT MALAYSIA**  
**IBU PEJABAT LAUT**  
**PETI SURAT 12, JALAN LIMBUNGAN**  
**42007 PELABUHAN KLANG**  
**SELANGOR DARUL EHSAN**



## **NOTICE TO MARINERS      NTM 103(T) /2022**

Telefon           : 03-3346 7777      Emel               : [kpgr@marine.gov.my](mailto:kpgr@marine.gov.my)  
Faksimili        : 03-3168 5289      Laman Web      : <http://www.marine.gov.my>

---

Authority           : Director of Marine, Malaysia

Position           : Malacca Straits

Charts Affected   : MAL 521 & MAL 5123  
                          BA 2403

---

### **PIAI BUOY MISSING TANJUNG PELEPAS PORT**

---

Mariners are advised that Tanjung Piai buoy was missing from its position. The details are as follows: -

Name               : **Piai Buoy**

Position           : **Lat. 01° 14.280' N**  
**Long. 103° 29.730' E**

Light Characteristic : **Fl(1)Y 5s**

Mariners are advised to navigate with caution when in the vicinity.

**(EMIZUL FADLY BIN MASDEK)**

for The Director General,  
Marine Department Malaysia.

28<sup>th</sup> July 2022

---

*Safer Ships, Secure Ports, Cleaner Seas*



CERTIFIED TO ISO 9001:2015  
CERT. NO.: QMS 03602