



**HYDROGRAPHIC OFFICE  
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS  
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422  
Website: [www.marine.gov.my](http://www.marine.gov.my)



**BORNEO NORTH WEST COAST**

**\*99/2022 – STARBOARD LATERAL MARK - SIP9 BUOY, SAMALAJU PORT -  
RESTORED TO NORMAL AND MOVE**

Starboard Lateral Mark - SIP9 Buoy, Samalaju Port has been restored to normal and move from 03°34'41.800"N 113°18'38.300"E to 03°34'41.118"N 113°18'38.213"E.

2. Notice 76/2022(T) is hereby cancelled and mariners are advised to update their affected charts accordingly.

Charts : SAR 501 & SAR 5001  
Source : Sarawak Region Marine Department  
Date : 23<sup>rd</sup> August 2022

**"BERKHIDMAT UNTUK NEGARA"**

**[ RADUAN BIN SERAP ]**  
For Director of Marine Sarawak

**"Safer Ships, Secure Ports, Cleaner Seas"**



Cert. No: ISO 9001-0047621, ISO 9001-0047600