



NOTICE TO MARINERS NTM 36(T)/2023

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
 Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Johor Waters

Charts Affected : MAL 515
 BA 2413

**ASIA PACIFIC GATEWAY (APG) S9 OPN 3 SUBMARINE CABLE REPAIR
 JOHOR WATERS**

Mariners are advised that submarine cable repair work for Asia Pacific Gateway (APG) system is being carried out in Johor Waters. The details are as follows:

Duration : 19th March – 14th April 2023

Vessels Involved:

Name : Asean Explorer Type : Cable Laying Vessel Flag : Indonesia IMO No: 9236676	Name : Aishah 2 Type : License Boat P.O. R: Pasir Gudang License No: JPG00325K
--	---

Area: Area: The work area is enclosed by an imaginary lines connecting the following points:

Point	Latitude	Longitude
ESTIMATED FAULT	02° 01.205'N	104°45.615' E
CX OOS SHT A	02° 04.193'N	104°46.573' E
CX IS C2C seg 7	02° 07.910'N	104°46.041' E
CX OOS APCN seg B14	02° 11.688'N	104°46.078' E
1	01° 51.293'N	104°41.242' E
2	02° 03.781'N	104°46.067' E

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
 CERT. NO.: QMS 03602

3	02° 07.012'N	104° 46.103'E
4	02° 08.171'N	104° 45.112'E
5	02° 08.951'N	104° 44.757'E
6	02° 09.467'N	104° 44.731'E
7	02° 10.885'N	104° 45.018'E
8	02° 12.386'N	104° 45.850'E
9	02° 11.714'N	104° 46.688'E
10	02° 10.330'N	104° 45.934'E
11	02° 09.390'N	104° 45.785'E
12	02° 08.397'N	104° 46.142'E
13	02° 07.418'N	104° 47.091'E
14	02° 03.224'N	104° 46.980'E
15	01° 50.869'N	104° 42.216'E

Above coordinates are referenced to Datum: WGS-84

Mariners are advised to navigate with caution when in the vicinity and keep clear of the working area.

(MOHD IZUAN BIN ISNAN)
for The Director General,
Marine Department Malaysia.
19th March 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602