



**MALAYSIA MARINE DEPARTMENT**  
**MARINE HEADQUATERS**  
**P.O BOX 12, JALAN LIMBUNGAN**  
**42007 PELABUHAN KLANG**  
**SELANGOR DARUL EHSAN**  
**MALAYSIA**



**PENINSULAR NOTICE TO MARINERS NTM 162/2023**

Telefon : 03-3346 7777 Emel : [kpqr@marine.gov.my](mailto:kpqr@marine.gov.my)  
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

---

Authority : Director of Marine, Malaysia

Position : Malacca Waters

Charts Affected : MAL 532  
BA 3946

---

**SUNGAI UDANG FAIRWAY LIGHT BUOY ALTERED IN POSITION  
MALACCA WATERS**

---

Mariners are advised that Sungai Udang Fairway light buoy has been altered in position. Details are as follows:

Name : **Sungai Udang Fairway**

Position : **Lat. 02° 11.503' N**  
**Long. 102° 04.201' E**

Elevation : 3.5 metres

Range of Light : 5 Nm

Light Characteristic : L.FL.W.10s

Mariners are advised to navigate with caution when in the vicinity.  
This notice cancels NTM 31(T)/2023.

**(EMIZUL FADLY MASDEK)**  
for The Director General,  
Malaysia Marine Department  
17<sup>th</sup> July 2023

---

*Safer Ships, Secure Ports, Cleaner Seas*



CERTIFIED TO ISO 900:2015  
CERT. NO.: QMS 03602