



**JABATAN LAUT MALAYSIA**  
IBU PEJABAT LAUT  
PETI SURAT 12, JALAN LIMBUNGAN  
42007 PELABUHAN KLANG  
SELANGOR DARUL EHSAN



**PENINSULAR NOTICE TO MARINERS - NTM139/2023**

Telefon : 03-3346 7777 Emel : [kpqr@marine.gov.my](mailto:kpqr@marine.gov.my)  
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

---

Authority : Director of Marine, Malaysia

Position : South China Sea

Charts Affected : MAL 654  
BA 3446

---

**BATUAN TOKONG DAYAK LIGHT BEACON RESTORED TO NORMAL  
SOUTH CHINA SEA**

---

Mariners are advised that Batuan Tokong Dayak Light Beacon has been restored to normal.

Name : Batuan Tokong Dayak  
Position : Latitude 04° 46.937' N  
Longitude 103° 41.333' E  
Light Characteristic : FL.W.3s

Mariners are advised to navigate with caution in the area.

This notice cancels NTM 122(T)/2023.

**(MOHD IZUAN BIN ISNAN)**  
for The Director General,  
Malaysia Marine Department.  
26<sup>th</sup> June 2023

---

*Safer Ships, Secure Ports, Cleaner Seas*



CERTIFIED TO ISO 9001:2015  
CERT. NO.: QMS 03602