



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUATERS
P.O BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA



PENINSULAR NOTICE TO MARINERS NTM 161/2023

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : Pulau Tioman, South China Sea
Charts Affected : MAL 6257
BA 3445

**MARINA TIOMAN BREAKWATER STARBOARD LIGHT BEACON
RESTORED TO NORMAL
SOUTH CHINA SEA**

Mariners are advised that Marina Tioman Breakwater Starboard light beacon has been restored to normal. Details are as follows:

Name : Marina Tioman Breakwater Starboard
Position : Lat. 02° 49.126' N
Long. 104° 09.376' E
Light Characteristic : Q.G

Mariners are advised to navigate with caution when in the vicinity.
This notice cancels NTM 147(T)/2023.

(EMIZUL FADLY MASDEK)
for The Director General,
Malaysia Marine Department
17th July 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 900:2015
CERT. NO.: QMS 03602