



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUATERS
P.O BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA



PENINSULAR NOTICE TO MARINERS NTM 137/2023

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Perlis Waters

Charts Affected : MAL 5625
BA 3943

**KUALA PERLIS 2G LIGHT BUOY REPLACED IN POSITION
PERLIS WATERS**

Mariners are advised that Kuala Perlis 2G light buoy has been reposition and restored to normal. Details are as follows:

Name : Kuala Perlis 2G
Position : Lat. 06° 24.050' N
Long. 100° 05.966' E
Light Characteristic : Fl.G.4s

Mariners are advised to navigate with caution when in the vicinity.
This notice cancels NTM 28(T)/2023.

(EMIZUL FADLY MASDEK)
for The Director General,
Malaysia Marine Department
23rd June 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 900:2015
CERT. NO.: QMS 03602