



**HYDROGRAPHIC OFFICE
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422
Website: www.marine.gov.my



BORNEO NORTH WEST COAST

***150/2023 – STARBOARD LATERAL MARK - SIP7 BUOY, SAMALAJU PORT -
RESTORED TO NORMAL AND MOVE**

Starboard Lateral Mark - SIP7 Buoy has been restored to normal and move from
03°35'10.700"N 113°18'09.900"E to 03°35'10.600"N 113°18'09.600"E.

2. Notice 142/2022(T) is hereby cancelled and mariners are advised to update their
affected charts accordingly.

Charts : SAR 6, SAR 501 & SAR 5001

Source : Sarawak Region Marine Department

Date : 5th October 2023

"BERKHIDMAT UNTUK NEGARA"

[ABDUL AZIZ BIN ABD MAJID]

For Director of Marine Sarawak

Safer Ships, Secure Ports, Cleaner Seas



Cert No: ISO 9001-0047600, ISO 9001-0047621