



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUARTERS
PO BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA



PENINSULAR NOTICE TO MARINERS

NTM 223/2022

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Kertih, Terengganu

Charts Affected : Mal 6441
BA 3482

PATON BANK LIGHT BUOY RESTORED TO NORMAL
KERTIH, TERENGGANU WATERS

Mariners are advised that Paton Bank light buoy has been restored to normal. The details are as follows:

1. Name : Paton Bank
Position : Lat. 04° 32.670' N, Long. 103° 31.370' E
Light Characteristic : FL.R.5S

Mariners are advised to navigate with caution in the area.
This notice cancels NTM 175(T)/2023.

(EMIZUL FADLY MASDEK)
for The Director General,
Malaysia Marine Department.
27th September 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602