



**MALAYSIA MARINE DEPARTMENT**  
**MARINE HEADQUARTERS**  
**P.O BOX 12, JALAN LIMBUNGAN**  
**42007 PELABUHAN KLANG**  
**SELANGOR DARUL EHSAN**  
**MALAYSIA**



**PENINSULAR NOTICE TO MARINERS    NTM 237(T)/2023**

Telefon           : 03-3346 7777    Emel               : [kpgr@marine.gov.my](mailto:kpgr@marine.gov.my)  
Faksimili        : 03-3168 5289    Laman Web      : <http://www.marine.gov.my>

Authority           : Director of Marine, Malaysia

Position           : Malacca Straits

Charts Affected   : MAL 532  
                          BA 3946

**SEPAT RESILIENT LIGHT BEACON RACON TEMPORARILY WITHDRAWN  
MALACCA STRAITS**

Mariners are advised that Sepat resilient light beacon **Racon** has been temporarily withdrawn. The details are as follows:

Name                : **Sepat RLB Racon**

Position            : **Lat. 02° 33.889' N, Long. 101° 23.363' E**  
                          (*Datum: WGS-84*)

Sector               : **360°**

Morse Code signal   : **“ C “**

Mariners are advised to navigate with caution when in the vicinity.

**(EMIZUL FADLY BIN MASDEK)**

for The Director General,  
Malaysia Marine Department.

6<sup>th</sup> October 2023

*Safer Ships. Secure Ports. Cleaner Seas*



CERTIFIED TO ISO 900:2015  
CERT. NO.: QMS 03602