



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUATERS
P.O BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA



PENINSULAR NOTICE TO MARINERS NTM 224/2023

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : South China Sea, Kerteh Port
Charts Affected : MAL 6441
BA 3482

**KERTEH PORT NO 2R LIGHT BUOY RESTORED TO NORMAL
TERENGGANU WATERS**

Mariners are advised that Kertih Port No 2R light buoy has been restored to normal.
Details are as follows:

Name : Kertih Port No 2R
Position : Lat. 04° 35.921' N
Long. 103° 27.668' E
Light Characteristic : Q.R

Mariners are advised to navigate with caution when in the vicinity.
This notice cancels NTM 206(T)/2023.

(EMIZUL FADLY MASDEK)
for The Director General,
Malaysia Marine Department
27th September 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 900:2015
CERT. NO.: QMS 03602