



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUARTERS
P.O BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA



PENINSULAR NOTICE TO MARINERS NTM 236/2023

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : Malacca Straits, Port Dickson Waters
Charts Affected : MAL 5239
BA 3946

**PORT DICKSON FAIRWAY LIGHT BUOY RESTORED TO NORMAL
MALACCA STRAITS**

Mariners are advised that Port Dickson Fairway light buoy has been restored to normal.
Details are as follows:

Name : **Port Dickson Fairway**
Position : **Lat. 02° 30.000' N**
Long. 102° 42.766' E
(Above Coordinates are referenced to Datum: WGS-84)
Light Characteristic : **LFI.W.10s**

Mariners are advised to navigate with caution when in the vicinity.
This notice cancels NTM 112(T)/2023.

(EMIZUL FADLY MASDEK)
for The Director General,
Malaysia Marine Department
6th October 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602