



**MALAYSIA MARINE DEPARTMENT**  
**MARINE HEADQUATERS**  
**P.O BOX 12, JALAN LIMBUNGAN**  
**42007 PELABUHAN KLANG**  
**SELANGOR DARUL EHSAN**  
**MALAYSIA**



**PENINSULAR NOTICE TO MARINERS    NTM 277/2023**

Telefon           : 03-3346 7777    Emel               : [kpqr@marine.gov.my](mailto:kpqr@marine.gov.my)  
Faksimili       : 03-3168 5289    Laman Web      : <http://www.marine.gov.my>

---

Authority           : Director of Marine, Malaysia

Position           : Johor Waters, Pengerang

Charts Affected   : MAL 515  
                          BA 2403

---

**PG 1-2 & SB3 LIGHT BUOY PERMANENTLY WITHDRAWN**  
**JOHOR WATERS**

---

Mariners are advised that PG 1-2 light buoy and SB-3 light buoy has been permanently withdrawn. The details are as follows:

Name                : **PG 1-2**  
Position            : **Lat. 01° 19.548' N, Long. 104° 09.234' E**  
Light Characteristic : **FL.R.5s**  
Description         : **Port Hand**

Name                : **SB-3**  
Position            : **Lat. 01° 19.126' N, Long. 104° 11.854' E**  
Light Characteristic : **FL(2).G.6s**  
Description         : **Starboard Hand Lateral Mark**

Mariners are advised to navigate with caution.

**(EMIZUL FADLY MASDEK)**  
for The Director General,  
Marine Department Malaysia.  
24<sup>th</sup> November 2023