



**NOTICE TO MARINERS**

**NTM 33(R)/2022**

Telefon : 03-3346 7777 Emel : [kpgr@marine.gov.my](mailto:kpgr@marine.gov.my)  
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Johor Waters

Charts Affected : MAL 515  
BA 2403

**CORRIGENDUM TO NTM 33/2022 LIGHT BUOY AND BEACON  
ESTABLISHED IN POSITION  
PENGERANG TERMINAL 2, JOHOR WATERS**

Mariners are advised that light buoy and beacon have been established in position in Pengerang Terminal 2, Johor Waters. The details are as follows:

1. Name : **LSL2-A LEADING SECTOR LIGHT**  
Position : Lat 01° 20.384' N, Long. 104° 10.691' E  
Light Characteristic : ISO 8s  
Type : Beacon
2. Name : **LSL2-B LEADING SECTOR LIGHT**  
Position : Lat 01° 20.207' N, Long. 104° 11.063' E  
Light Characteristic : ISO 4s  
Type : Beacon
3. Name : **LSL2-C LEADING SECTOR LIGHT**  
Position : Lat 01° 20.033' N, Long. 104° 10.547' E  
Light Characteristic : ISO 8s  
Type : Beacon
4. Name : **LSL2-D LEADING SECTOR LIGHT**  
Position : Lat 01° 19.996' N, Long. 104° 11.231' E  
Light Characteristic : ISO 4s  
Type : Beacon
5. Name : **DLSL-1 DREDGE LIMIT SECTOR LIGHT**  
Position : Lat 01° 19.751' N, Long. 104° 11.242' E  
Light Characteristic : FL.Y.3s  
Type : Beacon

6. Name : **DLSL-2 DREDGE LIMIT SECTOR LIGHT**  
 Position : Lat 01° 19.417' N, Long. 104° 10.930' E  
 Light Characteristic : FL.Y.3s  
 Type : Beacon
7. Name : **PS-1 PORT BUOY**  
 Position : Lat 01° 19.946' N, Long. 104° 10.440'E  
 Light Characteristic : FL.R.2s  
 Type : Port Hand Lateral Mark
8. Name : **PS-2 PORT BUOY**  
 Position : Lat 01° 19.741' N, Long. 104° 10.260'E  
 Light Characteristic : FL.R.5s  
 Type : Port Hand Lateral Mark
9. Name : **PS-3 PORT BUOY**  
 Position : Lat 01° 19.131' N, Long. 104° 10.663'E  
 Light Characteristic : FL(2).R.6s  
 Type : Port Hand Lateral Mark
10. Name : **SB-1 STARBOARD BUOY**  
 Position : Lat 01° 19.741' N, Long. 104° 11.619'E  
 Light Characteristic : FL.G.2s  
 Type : Starboard Hand Lateral Mark
11. Name : **SB-2 STARBOARD BUOY**  
 Position : Lat 01° 19.602' N, Long. 104° 11.753'E  
 Light Characteristic : FL(2).G.10s  
 Type : Starboard Hand Lateral Mark
12. Name : **SB-3 STARBOARD BUOY**  
 Position : Lat 01° 19.126' N, Long. 104° 11.854'E  
 Light Characteristic : FL(2).G.6s  
 Type : Starboard Hand Lateral Mark
13. Name : **HL-1 HAZARD LIGHT**  
 Position : Lat 01° 19.741' N, Long. 104° 10.596'E  
 Light Characteristic : FL.G.5s  
 Type : Beacon

14. Name : **HL-2 HAZARD LIGHT**  
Position : Lat 01° 19.748' N, Long. 104° 11.242'E  
Light Characteristic : FL.G.5s  
Type : Beacon

15. Name : **HL-3 HAZARD LIGHT**  
Position : Lat 01° 19.428' N, Long. 104° 10.493'E  
Light Characteristic : FL.G.5s  
Type : Beacon

16. Name : **HL-4 HAZARD LIGHT**  
Position : Lat 01° 19.426' N, Long. 104° 11.371'E  
Light Characteristic : FL(2).R.10s  
Type : Beacon

Mariners are advised to navigate with caution when in the vicinity.  
This notice replace NTM 33/2022.

**(EMIZUL FADLY MASDEK)**  
for The Director General,  
Malaysia Marine Department  
3<sup>rd</sup> November 2023

