



**MALAYSIA MARINE DEPARTMENT**  
**MARINE HEADQUARTERS, MENARA DIUS API**  
**PT 664, JALAN LIMBUNGAN**  
**42007 PELABUHAN KLANG**  
**SELANGOR DARUL EHSAN**  
**MALAYSIA**



**PENINSULAR NOTICE TO MARINERS NTM 121/2024**

Telefon : 03-3346 7777 Emel : [kpgr@marine.gov.my](mailto:kpgr@marine.gov.my)  
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Rompin, South China Sea

Charts Affected : MAL 635,  
BA 3445

**KUALA ROMPIN FAIRWAY LIGHTBOUY RESTORED TO NORMAL  
PAHANG WATERS**

Mariners are advised that Kuala Rompin Fairway light buoy is unlit. The details are as follows:

**Name : Kuala Rompin Fairway(KRF)**

**Position : Lat. 02° 50.000' N  
Long. 103° 30.000' E**

**Light Characteristic : LFI.W.10s**

Mariners are advised to navigate with caution when in the vicinity.

This notice cancels/supersede NTM 138(T)/2024.

**(TS. MUHAMMAD FADHLI BIN MAKHTAR)**  
for The Director General,  
Malaysia Marine Department  
4<sup>th</sup> November 2024.