



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 62/2023

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : Malacca Strait
Charts Affected : MAL 532
 BA 3946

SEPAT RLB LIGHTBEACON RESTORED TO NORMAL MALACCA STRAIT

Mariners are advised that Sepat RLB Lightbeacon has been restored to normal.

Name : Sepat RLB Lightbeacon
Position : Lat. 02° 33.889' N
 Long. 101° 23.363' E
Characteristic : Q.W

Mariners are advised to navigate with caution.

This Notice cancels NTM 30(T)/2023

(MOHD IZUAN BIN ISNAN)
for The Director General,
Marine Department Malaysia.
16th April 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602