



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 64/2023

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : South China Sea

Charts Affected : MAL 654
 BA 3446

CHENDERING SOUTH LIGHT BEACON RESTORED TO NORMAL SOUTH CHINA SEA

Mariners are advised that Chendering South Light Beacon has been restored to normal.

Name : Chendering South Light Beacon

Position : Lat. 05° 15.491' N
 Long. 103° 11.052' E

Light Characteristic : Fl. R4s

Mariners are advised to navigate with caution when in the vicinity.

This Notice cancels NTM 60(T)/2023

(MOHD IZUAN BIN ISNAN)
for The Director General,
Marine Department Malaysia.
18th April 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602