



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 76/2023

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : Pengerang, Johor Waters.
Charts Affected : MAL 6124, MAL 515
 BA 2403

POH LAI LIGHT BUOY RESTORED TO NORMAL JOHOR WATERS

Mariners are advised that an Isolated danger mark light buoy has been restored to normal. The details are as follows:

Name : Poh Lai
Position : **Lat. 01° 17.940' N,**
 Long. 104° 07.246' E
Light Characteristic : Fl. (2).W.10s
Type of Mark : **Isolated Danger Mark**

Mariners are advised to navigate with caution when in the vicinity

This Notice cancels NTM 43(T)/2023

(EMIZUL FADLY BIN MASDEK)
for The Director General,
Marine Department Malaysia.
17th April 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602