



**MALAYSIA MARINE DEPARTMENT**  
**MARINE HEADQUARTERS**  
**P.O BOX 12, JALAN LIMBUNGAN**  
**42007 PELABUHAN KLANG**  
**SELANGOR DARUL EHSAN**  
**MALAYSIA**



**PENINSULAR NOTICE TO MARINERS NTM 112(T)/2023**

Telefon : 03-3346 7777 Emel : [kpgr@marine.gov.my](mailto:kpgr@marine.gov.my)  
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia  
Position : Malacca Straits, Port Dickson Waters  
Charts Affected : MAL 5239  
BA 3946

**PORT DICKSON FAIRWAY LIGHT BUOY UNLIT  
MALACCA STRAITS**

Mariners are advised that Port Dickson Fairway light buoy is unlit. Details are as follows:

Name : Port Dickson Fairway  
Position : Lat. 02° 30.000' N  
Long. 102° 42.766' E  
Light Characteristic : LFI.W.10s

Mariners are advised to navigate with caution when in the vicinity.

**(Ts. MUHAMMAD FADHLI BIN MAKHTAR)**  
for The Director General,  
Malaysia Marine Department  
31<sup>st</sup> May 2023

*Safer Ships, Secure Ports, Cleaner Seas*



CERTIFIED TO ISO 9001:2015  
CERT. NO.: QMS 03602