



**MALAYSIA MARINE DEPARTMENT**  
**MARINE HEADQUARTERS**  
P.O BOX 12, JALAN LIMBUNGAN  
42007 PELABUHAN KLANG  
SELANGOR DARUL EHSAN  
MALAYSIA



**PENINSULAR NOTICE TO MARINERS NTM 113/2023**

Telefon : 03-3346 7777 Emel : [kpgr@marine.gov.my](mailto:kpgr@marine.gov.my)  
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Lumut, Perak Waters

Charts Affected : MAL 5425  
BA 3944

**SELAT 2G & SELAT 2R LIGHT BUOY RESTORED TO NORMAL  
LUMUT, PERAK WATERS**

Mariners are advised that Selat 2G and Selat 2R Light Buoy has been restored to normal. Details are as follows:

Name : **Selat 2R**  
Position : **Lat. 04° 15.153' N**  
**Long. 100° 34.728' E**  
Light Characteristic : **Fl.R.3s**

Name : **Selat 2G**  
Position : **Lat. 04° 15.029' N**  
**Long. 100° 34.758' E**  
Light Characteristic : **Fl(2+1).G.10s**

Mariners are advised to navigate with caution when in the vicinity.  
This notice cancels NTM 13(T)/2022 & NTM 157(T)/2021.

**(EMIZUL FADLY MASDEK)**  
for The Director General,  
Malaysia Marine Department  
31<sup>th</sup> May 2023



**CERTIFIED TO ISO 900:2015**  
**CERT. NO.: QMS 03602**