



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



PENINSULAR NOTICE TO MARINERS - NTM122(T)/2023

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : South China Sea

Charts Affected : MAL 654
BA 3446

BATUAN TOKONG DAYAK LIGHT BEACON UNLIT
SOUTH CHINA SEA

Mariners are advised that Batuan Tokong Dayak Light Beacon is unlit.

Name : Batuan Tokong Dayak
Position : Latitude 04° 46.937' N
Longitude 103° 41.333' E
Light Characteristic : FL.W.3s

Mariners are advised to navigate with caution in the area.

(MOHD IZUAN BIN ISNAN)
for The Director General,
Malaysia Marine Department.
8th June 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602