



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



PENINSULAR NOTICE TO MARINERS NTM 124/2023

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Pengerang, Johor Waters.

Charts Affected : MAL 6124, MAL 515
 BA 2403

**POH LAI LIGHT BUOY REPLACED IN POSITION
JOHOR WATERS**

Mariners are advised that an isolated danger mark light buoy has been restored to normal. The details are as follows:

Name : Poh Lai

Position : Lat. 01° 17.680' N
Long. 104° 11.090' E

Light Characteristic: Fl.(2).W.10s

Type of Mark : Isolated Danger Mark

Mariners are advised to navigate with caution when in the vicinity.
This notice cancels NTM 76/2023.

(EMIZUL FADLY MASDEK)
for The Director General,
Marine Department Malaysia.
14th June 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602