



PENINSULAR NOTICE TO MARINERS NTM 126/2023

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
 Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Perak Waters

Charts Affected : MAL 5425
 BA 3944

**VALE 1,2, 3, 4,5 & 6 LIGHT BUOY ALTERED
 PERAK WATER**

Mariners are advised that Vale 1, 2, 3, 4, 5 & 6 Light buoy characteristic has been altered. Details are as follows:

Light Buoy	Position	Current Light Characteristic	New Light Characteristic
VALE 1	04° 08.868' N 100° 33.841' E	Oc(2+1).G.15s	FL (2+1) . G. 15s
VALE 2	04° 09.119' N 100° 33.669' E	Oc(2+1).R.15s	FL (2+1) . R. 15s
VALE 3	04° 08.949' N 100° 34.446' E	Oc(2+1).G.15s	FL (2+1) . G. 15s
VALE 4	04° 09.196' N 100° 34.443' E	Oc(2+1).R.15s	FL (2+1) . R. 15s
VALE 5	04° 09.029' N 100° 35.100' E	Oc(2+1).G.15s	FL (2+1) . G. 15s
VALE 6	04° 09.292' N 100° 35.093' E	Oc(2+1).R.15s	FL (2+1) . R. 15s

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 900:2015
 CERT. NO.: QMS 03602

Mariners are advised to navigate with caution when in the vicinity.

This notice cancels **NTM 118(T)/2023, NTM 119(T)/2023 & NTM 120(T)2023.**

(EMIZUL FADLY BIN MASDEK)

for The Director General,
Malaysia Marine Department
16th June 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 900:2015
CERT. NO.: QMS 03602