



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUARTERS, MENARA DIUS API
PT 664, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA



PENINSULAR NOTICE TO MARINERS NTM 151/2024

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Rompin, South China Sea

Charts Affected : MAL 635,
BA 3445

**KUALA ROMPIN FAIRWAY LIGHTBOUY RESTORED TO NORMAL
PAHANG WATERS**

Mariners are advised that Kuala Rompin Fairway light buoy has been restored to normal. The details are as follows:

Name : Kuala Rompin Fairway (KRF)

**Position : Lat. 02° 50.000' N
Long. 103° 30.000' E**

Light Characteristic : LFI.W.10s

Mariners are advised to navigate with caution when in the vicinity.

(EMIZUL FADLY MASDEK)
for The Director General,
Malaysia Marine Department
11th August 2024.