



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUARTERS, MENARA DIUS API
P.O BOX 664, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA



PENINSULAR NOTICE TO MARINERS NTM 192 / 2024

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : South China Sea, Kerteh Port
Charts Affected : MAL 6436
 BA 1374

**KERTIH NORTH PORT LIMIT LIGHT BUOY RESTORED TO NORMAL
SOUTH CHINA SEA**

Mariners are advised that Kertih North Port Limit Light Buoy has been restored to normal. The details are as follows:

Name : **Kertih North Port Limit (KNPL)**
Position : **Lat. 04° 37.000' N**
 Long 103° 31.000' E
 (Datum: WGS-84)
Light Characteristic : **Fl(4)Y.10s**

Mariners are advised to navigate with caution when in the vicinity.
This notice cancels NTM 147(T)/2024.

(EMIZUL FADLY MASDEK)
for The Director General,
Malaysia Marine Department.
1st October 2024