



**JABATAN LAUT MALAYSIA**  
**IBU PEJABAT LAUT**  
**PETI SURAT 12, JALAN LIMBUNGAN**  
**42007 PELABUHAN KLANG**  
**SELANGOR DARUL EHSAN**



## **PENINSULAR NOTICE TO MARINERS NTM 20 / 2024**

Telefon : 03-3346 7777 Emel : [kpgr@marine.gov.my](mailto:kpgr@marine.gov.my)  
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

---

Authority : Director of Marine, Malaysia  
Position : Pengerang, Johor Waters.  
Charts Affected : MAL 5123, MAL 515  
BA 2403

---

### **POH LAI LIGHT BUOY RESTORED TO NORMAL JOHOR WATERS**

Mariners are advised that Poh Lai light buoy has been restored to normal. are as follow:

Name : **Poh Lai**  
Position : **Lat 01° 17.730' N**  
**Long 104° 11.202' E**  
Light Characteristic : **Fl.(2).W.10s**  
Type of Mark : **Isolated Danger Mark**

Mariners are advised to navigate with caution when in the vicinity.

This notice cancels Peninsular Notice to Mariners NTM 10(T)/ 2024

**(TS. MUHAMMAD FADHLI BIN MAKHTAR)**  
for The Director General,  
Marine Department Malaysia.  
29<sup>st</sup> January 2024

---

*Safer Ships, Secure Ports, Cleaner Seas*



CERTIFIED TO ISO 9001:2015  
CERT. NO.: QMS 03602