



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUARTERS
PO BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



PENINSULAR NOTICE TO MARINERS

NTM 295/2023

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Malacca Straits, Port Klang.

Charts Affected : MAL 5300
BA 3945

**SOUTH FAIRWAY LIGHT BUOY REPLACED IN POSITION
PORT KLANG**

Mariners are advised that South Fairway light buoy has been replaced in position.

Name : South Fairway
Position : Lat. 02° 48.999' N
Long. 101° 14.800' E
Light Characteristic : L.Fl.10s

Mariners are advised to navigate with caution in the area.
This NTM cancels NTM 291(T)/2023.

(EMIZUL FADLY MASDEK)
for The Director General,
Marine Department Malaysia.
16th December 2023
